

5 Line Phase Stepper Motor



the features of four-wire five-phase stepper motor driving board: use ULN2003 high power Darlington chip to drive stepper motor driver; B, C, A, D LEDs indicate the state of the working four-phase stepper motor; set with the standard interface of stepping motor which can be directly inserted in the use.